



Failures, fiascos and fires: How to avoid trouble from manufacturing, through design, to installation

Quality Roundtable – Solar Power International 2019



Agenda

Part I

2:00

Welcome and introductions

2:05

Opening presentation from Initiative Partner
DuPont

2:15

Presentation of quality cases with moderated
audience discussion

2:45

**PANEL DISCUSSION: All about the BoM: The role of
bill of materials in module quality and field
performance**

Agenda

Part II

pv magazine group

3:25

PRESENTATION of quality cases with moderated audience discussion

3:40

DISCUSSION Best practices to ensure maximum tracker uptime

3:50

PANEL DISCUSSION: Component selection and installation practices to avoid fires

4:25

Closing remarks

Networking

Opening presentation





Kaushik Roy Choudhury
Senior Scientist and Project Leader



Sept 25, 2019

Materials choices to avoid field failures

Dr. Kaushik Roy Choudhury
Technical Manager, Global PV Reliability

DuPont Photovoltaic Materials Portfolio



**DuPont™
Solamet®** | **30+**
METALLIZATION PASTES | YEARS
RELIABLE INNOVATION PARTNER



**DuPont™
Tedlar®** | **30+**
BASED BACKSHEETS | YEARS
FIELD-PROVEN PERFORMANCE




**Dow
Corning™** | **30+**
SILICON-BASED PV SOLUTIONS | YEARS
SERVING THE SOLAR INDUSTRY

Delivering Quality for 30+ Years
Proven Performance (efficient + reliable)
Driving Lower LCOE for Higher Return

Levelized Cost of Energy (LCOE)

A prime metric for any market with eyes on long-term return



Expectation All modules need to meet claims for degradation and performance over lifetime (25-30+ years)

DuPont global field reliability program

- Quantitative analysis: components, materials, age, failure mode
- Post-inspection analytical characterization
- Collaborative: field partners, developers, government labs, universities



Improved accelerated tests and informed materials selection

6.5 M
modules

355
installations

1.8 GW
power




2019 Global field data analysis summary

- Nearly **2 GW** of fields inspected

- Total module defects observed: 34%
- Total backsheet defects observed: 14%
- Backsheet defects increased by 47% from 2018 analysis
- Cracking constitutes 66% of all backsheet defects

Module Defect Trends*




Cell / Interconnect: corrosion, hot spot, snail trails, broken interconnect, cracks, burn marks

Backsheet: outer layer (air side) and inner layer (cell side) cracking, delamination, yellowing

Encapsulant: discoloration, browning, delamination


Other: glass defects, loss of AR coating, junction box



Backsheet is one of the main component affected

* Actual module defects can be higher due to defects not picked up by initial inspection protocol (eg. cell cracking evidenced by subsequent EL or PID test)


Backsheet defects by degradation mode



Cracking and delamination can compromise electrical insulation of the module

Yellowing can be a precursor to mechanical degradation and embrittlement of many backsheet polymers


Sharp increase in backsheet defects after 4 years in the field



PA = Polyamide
PVDF = Polyvinylidene Difluoride
PET = Polyethylene Terephthalate
FEVE = Fluoroethylene Vinylether
PVF = Polyvinyl Fluoride; Tedlar®

Defects kick-in after a few years in the field
Not all materials are affected the same way

Higher temperatures and stronger UV accelerate defects



Higher backsheet defect rates in hot climates and in roof installations

Backsheet defects are 125% greater in hot climates

Backsheet defects are 75% greater for roof mounted systems


Learn from Mistakes

Global concern of Polyamide backsheet failure


Widespread backsheet through-cracks

- Prevalent along busbar ribbons, but extends to cell gaps and other regions with continued weathering
- Arcing and shorts often lead to localized burn-through and sometimes full module fires
- Reported inverter tripping and ground faults

6 years, NW
China



6 years, Sonoran Desert, USA



7 years, Sonoran Desert, USA



6 years, High Desert, Nevada, USA





* Backsheets were qualified by IEC testing

Impact of failures on You and Your System

Field failures after a few years threaten the long-term performance, durability and ROI

- Increase replacement costs and a system's LCOE
 - In an actual case study, replacing 6% of modules in a system is equal to an extra 0.5% annual degradation



Summary

- Field data from 1.8 GW of PV capacity across the globe demonstrates backsheet and cell defects are most prominent failure modes of PV modules
- Field failures after a few years can threaten long-term performance and ROI
- High temperature, strong UV irradiation and a fast growing market pose significant challenges to ensuring durable PV materials
- Attention to the quality of the Bill of Materials is critical
- Coupling field data with failure analysis should inform materials selection, and hopefully will help mitigate financial risks





Copyright © 2019 DuPont. All rights reserved. DuPont™ and the DuPont Oval Logo are trademarks or registered trademarks of DuPont or its affiliates.

Nothing contained herein shall be construed as a representation that any recommendations, use or resale of the product or process described herein is permitted and complies with the rules or regulations of any countries, regions, localities, etc., or does not infringe upon patents or other intellectual property rights of third parties.

The information provided herein is based on data DuPont believes to be reliable, to the best of its knowledge and is provided at the request of and without charge to our customers. Accordingly, DuPont does not guarantee or warrant such information and assumes no liability for its use. If this product literature is translated, the original English version will control and DuPont hereby disclaims responsibility for any errors caused by translation. This document is subject to change without further notice.



Quality cases

Sept 25, 2019

Quality case from the field

Learning opportunities

Dr. Kaushik Roy Choudhury

Technical Manager, Global PV Reliability

Mysterious faults

North America

- Service Time 7 years
- Location SW USA
- System size Utility scale, 12 MW
- Mounting configuration Ground mount
- Tracking Single-axis tracking
- Technology Mono-crystalline Si
- Climatic conditions High-desert



Indicators

- initial alarm raised with moisture ingress into modules leading to severe busbar and ribbon corrosion, ground faults, sometimes leading to module fires
- no issues with wiring, junction boxes, connectors
- further inspection by O&M revealed backsheet cracking in >75% of modules in field

Inspection results: the curious case of Mixed BOMs



Module backsheet and degradation identified on-site






Illumination from rear to reveal cracks in the inner layer

- prominent near busbars

Multiple Bills Of Material (four types of backsheets revealed, possibly other components) in the same model number with mixed serial numbers from a single module maker (BS1: 50% of field, BS2, BS3, BS4: ~16% each)

Different backsheets degrade differently though all are qualified by IEC certification

- **Three backsheets degrade significantly while one is completely defect free**



Inspection results: findings

All PVDF, PET, PA-based backsheets exhibited cracking

- 100% PA backsheets cracked along busbar ribbons, with several instances of burn-through
- 100% of PVDF backsheets have cracked outer layer leading to delamination
- 100% PET backsheets have cracked inner layer

No issues in Tedlar[®] backsheets

Cracking facilitates moisture ingress, often leading to busbar corrosion

Exposure of module interiors to moisture leads to shorting, inverter trips, power loss, and several instances of module fires

Inverter tripping most frequently observed after moist nights and rain

Failures cause serious safety and performance issues, ultimately resulting in significant economic losses


Field failures rising: know your BOM and do proper testing

Simple testing illustrates vulnerability of material

Cracked PVDF from the 12 MW field in NA




25 cycles 40 to 85° C



Crack extension after thermal cycling

Similar trends of backsheets failing in the field: rapid rise of cracking after break-in period



Similar pattern observed in defective PA and PET based backsheets:

accelerated testing in lab forms cracks → cracked modules subsequently observed in the field → **rapid rise in rate of cracking defects observed in field**

12 MW field: All modules being replaced: do your math (replacement, recycling cost, lost revenue)

Know your BOM!



Copyright © 2019 DuPont. All rights reserved. DuPont™ and the DuPont Oval Logo are trademarks or registered trademarks of DuPont or its affiliates.

Nothing contained herein shall be construed as a representation that any recommendations, use or resale of the product or process described herein is permitted and complies with the rules or regulations of any countries, regions, localities, etc., or does not infringe upon patents or other intellectual property rights of third parties.

The information provided herein is based on data DuPont believes to be reliable, to the best of its knowledge and is provided at the request of and without charge to our customers. Accordingly, DuPont does not guarantee or warrant such information and assumes no liability for its use. If this product literature is translated, the original English version will control and DuPont hereby disclaims responsibility for any errors caused by translation. This document is subject to change without further notice.



Tristan Erion-Lorico
Head of PV Module Business





MAKE DATA MATTER.


MODULE UNDERPERFORMANCE CASE STUDY

Tristan Erion-Lorico
Head of PV Module Business
PVEL




Building a 10 MW Project in California

- › Project constructed in 2011
- › The modules used were:
 - Covered by 5-year product warranty for workmanship
 - Covered by step performance guarantee for power loss – not linear
 - Produced by a financially unstable manufacturer
- › Operations began in late 2011



“Unforeseen” Issues Arise


- › Original owner sold the project to a third party in 2016
- › Microcracks soon began to cause hot spots and subsequent backsheet burns
- › **This created a safety hazard that had to be immediately remedied**




Issues observed after 5 years in field

Results of Heliolytics' Thermal Aerial Scan are Troubling

- › Owner conducts aerial thermal scan to quantify module defects
- › Half the site had excessive hot spots throughout; the other half had far fewer hot spots




Module Batch #1
Source: Heliolytics



Module Batch #2
Source: Heliolytics

Quality Issues Were Identified During Module Production

- › In 2011, PVEL completed serial defect testing for a batch of modules used in project
- › EL images of most samples showed signs of excessive microcracks originating at the cell bus bars, pointing to a soldering-related root cause
- › Thermal cycling caused the potential power loss to be realized
- › **PVEL's results were not fully considered and the module installation proceeded**



Post Thermal Cycling 200
Source: PVEL

Module Replacement Woes

- › Insolvent manufacturer with an uncooperative new owner
- › Insufficient warranty protection
- › 5-year workmanship warranty had just expired
- › Frame size and power class no longer available on the market, so needed to re-engineer for replacements
- › Replacing the worst cases of hot spot modules cost hundreds of thousands of dollars – adding up to more than two years of the entire **portfolio's** O&M budget





QUESTIONS AND OPEN DISCUSSION

Panel discussion

All about the BoM: The role of bill of materials in module quality and field performance





Kaushik Roy Choudhury

Senior Scientist and
Project Leader



Tara Doyle

Chief Commercial Officer



Hongbin Fang

Director of Product
and Technology



Paul Wormser

Vice President,
Operations



4

Quality cases



Proactive identification and risk management of systemic issues

Rob Andrews  **Heliolytics**

Summary:

A systemic fault is defined in this case as an issue occurring in a PV array which can be tracked back to a distinct process, manufacturing issue, or other correlating dataset on a site. This allows for identification and classification of these issues using statistical means, and therefore it is possible to assess the full risk profile of these types of faults.

In this case, we will present an example of a systemic fault identified in a project, how it was detected, and discuss recommended next steps were for mitigating risk in the system.

Findings

A routine aerial inspection was performed on a utility scale PV project. Based on initial findings, it was seen that approximately 0.2% of the site exhibited sub-module faults. This level of faults places the project in the 20th percentile of projects, meaning that 80% of comparable projects would have a fault rate less than this amount, indicating a potential warrantable issues.




Figure 1: Example of a sub-module defect seen from aircraft IR caused by diode activation or solder bond failure

Findings

Serial number data was also available for each module in this project, and was incorporated into the digital twin model for the array, and the results can be seen below, with the 'x' representing the location of the sub-module fault, and the shade of orange representing serial number bins.




Figure 2: Serial number correlation analysis, showing a correlation between diode faults (x) and serial number batch (shade of orange). The bar graph shows the difference in probability of failure between the light orange and dark orange serial number bins.

Findings

It can be seen that the location of sub-module faults correlated with a specific subset of serial numbers on site. Upon further investigation of the identified serial numbers, it was seen that all affected modules came from the same plant, production line and soldering machine. Upon further investigation with the manufacturer, it was identified that a soldering machine was out of calibration during manufacturing, affecting 1/5 of the modules on site.

Other common causes of systemic faults:

Some other common causes of systemic faults seen from aerial inspections along with the dataset used to correlate the failure are:

- Fuse failures caused by improper manufacturing techniques (Fuse Serial number)
- Connector failures caused by improper cross-mating (System as-builts/connector manifest)
- Connector failures caused by water and dirt ingress during installation (Date of installation)
- Module degradation due backsheet failure (Module Bill of Materials by serial number)
- Module degradation due to improper cell sorting (Date of manufacture)

Conclusions

It is common that failures in a PV system are not truly “stochastic” or random, but rather are being forced by a specific root cause. By utilizing advanced data and analysis tools, the random characteristics of a failure can be peeled away, and a more detailed root cause can be identified. This root cause can then be used to better identify recommended next steps and predict future performance of a component or a project.

In this specific case, this information allowed the customer to better identify underlying risks in the project, and to negotiate a more beneficial settlement to the warranty for these modules, which included a consideration for the potential of future module failures.

Questions

- What processes would have avoided this root cause during project development/construction/operations?
- What other sources of data can be useful in the identification of fault root causes?
- Do current warranty contracts include systemic failure clauses? If not, why not?

Discussion

Best practices to ensure maximum tracker uptime





Kent Whitfield

VP of Quality



Christian Roselund

U.S. editor



6 GW – How much is that?




Process Capability, Cpk	Percentage of good parts
1.0	99.7%
1.2	99.97%
1.33	99.99%

Three Peaks, UT

- 115 MW/week
 - ~50,000 Piers, slews, torque tubes
 - ~370,000 modules, rails, fasteners
- Cumulative worldwide installed PV as of 2006
- 56 systems like this 107MW site in Utah
- *What level of quality control is good enough?*

Where do we need to go?

Process capability at the start of HVM → continuous capability and SQC → SPC





Panel discussion

Component selection and installation practices to avoid fires



Dean Solon

Founder and CEO



Jan Mastny

Head of Global Sales, Solar
and Wind



Brian Mills

Product Manager
Photovoltaics



Kim Primerano

O&M Director

Longroad Energy

Networking session



pv magazine group



Failures, fiascos and fires: How to avoid trouble from manufacturing, through design, to installation

Quality Roundtable – Solar Power International 2019

